	RFQ:13-14\0023 dated 29.11.2013 REQUEST FOR QUOTATION FOR AMC FOR SWITCHING AND NETWORKING EQUIPMENTS										
S. No.	Document Reference	Page No	Clause No	Description in RFP	Clarification Sought	Additional Remarks (if any)	NPCI Comments				
1	RFP document			Response: Within 4 hours. Resolution: Next Business Day.	Response: Within 4 hours can be done for CISCO equipment but for other non-standard OEM equipments the response time is not available in this time frame. Please change the response time from 4hrs to 24 hrs and resolution time from NBD to 48 hrs.		No change in terms of RFP				
2	RFP document	9	3.1.12	To provide patches / upgrades of IOS during the period of AMC	This is a H/W AMC for which S/W patches are not part of scope. We can include it but this would increase the cost to a great extent as different skilled resources need to be deployed. If NPCI thinks this activity is very frequent then this high cost is justifiable else we suggest NPCI to take this activity on a on-call chargeable basis		No change in terms of RFP				
3	RFP document	13	6.8.1	Bids shall remain valid for a period of 180 days after the date of bid opening	Change to "Bids shall remain valid for a period of 60 days after the date of bid opening"	OEM is not giving price extension for 180 days at one time. NPCI can extend beyond 60 days if needed after vendors confirmation.	No change in terms of RFP				
4	RFP document	16	9.4.3	Tax rates	Please make provision to allow modified billing if taxes change in future.	If Taxes increase or decrease in future we have to follow the govt orders and bill NPCI accordingly. We cannot freeze tax rate for 3 years.	No change in terms of RFP				
5	RFP document	16	9.5	Penalty for delay in services	Penalty of Rs. 100/- per day shall be levied if the call is not resolved within 48 hrs. or 2 business day subjected to maximum 5 % of the quarterly billing value. For parts replacement cases additional 3 days to be given to order	The mentioned Penalty rates don't cover for replacement cases where new parts need to be ordered. Also please decrease the penalty cap limit & change from PO value to quarterly billing value.	No change in terms of RFP				
6		17	9.6.1	Payment for AMC shall be made quarterly in arrears	Change to "Payment for AMC shall be made quarterly in arrears or in advance if BG is submitted"		No change in terms of RFP				
7	RFP document	8	Annexu re- 2	Bidder should be a profit (profit after tax) making company in the last financial	 Please change the criteira to any one of the following: Bidder should have a positive networth in each of the last three financial years Bidders should have a positive cumulative net profit over last five financial years Bidders PBIT (Profit before Interest expense & taxes) for each of the last three financial years should be Positive Bidder should be profitable in at least 2 years during the last three financial years. 	Please alter the profitability criteria. We have made Profit before tax & interest but overall there is a loss in last FY due to one -time write-off. We can issue a solvency certificate if needed.	No change in terms of RFP				

S. No.	Document	Page	Clause	Description in RFP	Clarification Sought	Additional Remarks (if any)	NPCI Comments
	Reference	No	No				
8	RFQ Reference	10	3.2	Sr. No: 1	Need Brand and Exact Model No.		(NET00073)
	Number:			8-port KVM Switch			ATEN
	NPCI:RFQ:2013 -						Z399T105AD60186
	14/0023, Dated:						
	29.11.2013						
9				Sr. No: 2, 3, 4, 5, 13, 14, 15, 16 Static			Static Transfer Switch
				Transfer Switch			2)APC 5A1048T66902
							3)APC 5A1038T73684
							4)APC 5A1038T73686
							5)APC 5A1048T66939
							13)APC 5A1038T73581
							14)APC 5A1038T73732
							15)APC 5A1048T66913
							16)APC A1126TI7396
10				Sr. No: 6, 7 Catalyst Switch			6)Cisco Catalyst Switch FOC1422YOGF
							7)Cisco Catalyst Switch FOC1420Z2FV
11				Sr. No: 10 LTO4 Ext Tape Drive	Need Brand and Exact Model/Part Number.		LTO 4 Ext Tape drive 78R5501
					Also, if it's SAS/SCSI/Fibre Interface?		
12				Sr. No: 11, 12 Cisco Linksys Routers	Need Exact Model No.		11)Cisco Linksys routers 014J03202240
							12)Cisco Linksys routers 014J03202240